



Navigation Channel Condition Status Report - 13 February 2013

Marker	Mississippi	River Mile	Illinois River
LD 22 TW = 6.85 (0.61) ft at 02-13-2013 15:30 3 Day Forecast = 6.8 6.7 6.7 Forecast Date 02/13/13 11:21		301.0	
LD 24 Pool = 449.11 (0.06) ft at 02-13-2013 15:00 TW = 16.74 (0.72) ft at 02-13-2013 15:30 3 Day Forecast = 17 17 17 Forecast Date 02/13/13 11:21		273.5	
LD 25 Pool = 433.99 (-0.12) ft at 02-13-2013 15:00 TW = 16.60 (0.87) ft at 02-13-2013 15:30 3 Day Forecast = 16.7 16.7 16.7 Forecast Date 02/13/13 11:21		241.5	
Mel Price Pool = 419.22 (-0.16) ft at 02-13-2013 15:00 TW = 6.62 (1.14) ft at 02-13-2013 15:30 3 Day Forecast = 7 7 6.9 Forecast Date 02/13/13 11:21			
	Grafton		Illinois River
St. Louis Stage = 4.56 (2.22) ft at 02-13-2013 15:30 3 Day Forecast = 5 5.1 5.1 Forecast Date 02/13/13 11:35		201	
	Missouri River	Upper R. Lower R.	
	Lock 27		
	St. Louis	180	
Chester Stage = 7.57 (0.35) ft at 02-13-2013 15:30 3 Day Forecast = 8.3 9 9.1 Forecast Date 02/13/13 11:35			
			Kaskaskia R.
	Chester	110	
Cape Girardeau Stage = 13.31 (0.04) ft at 02-13-2013 15:30 3 Day Forecast = 13.9 15 15.4 Forecast Date 02/13/13 10:50			
MILE 26.5 - 26.1 - AIDS TO NAVIGATION Three can buoys have been reported not properly marking the channel between approximate Miles 26.5 and 26.1. Transit with caution.			
Cairo Stage = 32.67 (-2.40) ft at 02-13-2013 15:00 3 Day Forecast = 31.5 30.1 29.2 Forecast Date 02/13/13 10:50		52	
	Cape Girardeau SEMO Port		
			Ohio River
	Cairo		

MILE 56.0 - BRIDGE MAINTENANCE
Florence Highway Drawbridge; Work barges are located along the downstream left and right descending banks. No impacts to navigation are anticipated.

NOTICE TO NAVIGATION - RM 185.5 - L&D 27
The 1200 ft main lock will be closed for miter gate replacement and embedded metal repairs from 10 December 2012 til 1 March 2013. During this time, the 600 ft auxiliary lock will be open and the Government will provide the services of a helper boat to pull cuts from the 600 ft chamber.

MILE 95.2 - CHANNEL CONDITION
A can buoy has been reported not properly marking the channel, mid-channel, in the vicinity of Mile 95.2. Transit with caution.

MILE 89.2 - 87.2 - CHANNEL CONDITION
Scattered rock and a rock shelf have been reported between approximate Miles 89.2 and 87.2, along the can buoy line. The USACE has adjusted the buoys in the area leaving a channel that is approximately 350 feet wide in some locations. Transit with caution.

MILE 80.5 - 78.5 - CHANNEL CONDITION/SAFETY ZONE
The COTP Ohio Valley has established a Safety Zone from Mile 80.5 to Mile 78.5 to facilitate the USACE rock pinnacle removal operation. All vessels are prohibited from entering this zone unless permitted by the COTP Ohio Valley or a designated representative. It is anticipated that waterway closures will last from 12:00 midnight until 12:00 noon, daily. The vessel management group will manage vessel traffic. For closure and contact details, please see the nav notice at:
<http://www.navcen.uscg.gov/pdf/Inms/Inm0805r2013.pdf>

MILE 46.0 - 38.5 - CHANNEL CONDITION/SAFETY ADVISORY
The COTP Ohio Valley and the COTP Upper Mississippi River have issued a Safety Advisory due to rock pinnacle removal operations between approximate Miles 46.0 and 38.5. A vessel reporting scheme will be maintained by Coast Guard Sector Ohio Valley and Sector Upper Mississippi River, throughout the duration of rock removal operations. For communication details and additional information, see the nav notice at:
<http://www.navcen.uscg.gov/pdf/Inms/Inm0807r2013.pdf>

MILE 41.5 - MILE 38.0 - CHANNEL CONDITION/SAFETY ZONE
The COTP Ohio Valley has established a Safety Zone from Mile 41.5 to Mile 38.0 to due to low water. A vessel reporting scheme will be maintained by Coast Guard Sector Ohio Valley and Sector Upper Mississippi River, throughout the duration of rock removal operations. For communication details and additional information, see the nav notice at:
<http://www.navcen.uscg.gov/pdf/Inms/Inm0807r2013.pdf>

Dredge Status
Dredge Potter
- At Service Base

Channel Marker Status
Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.
The Pathfinder will be heading south to Cairo next week.

Additional Risks / Concerns
All mariners are advised that the Upper Mississippi River Waterways Action Plan Zone 28 (RM 109.9 to RM 185.0) is currently in the extreme low water action phase. Due to low river levels and shifting channels, there is an increase for potential groundings. Transit at a slow speed near fleeting areas. Heavy barges should be placed in the middle of tows. Transit with extreme caution. For additional info, contact the Coast Guard Sector UMR Command Center at 314-269-2332.

As the river falls, rock pinnacles at Thebes and Grand Tower increasingly become navigation hazards. For more information, [Click here](#)

Navigation Notices
Local Notice to Mariners

Current Weather
Highs in the high 50s to the low 30s; lows in the low 40s to upper teens. Chance of flurries to the north Thursday night to Friday and chance of rain Monday to Tuesday.
[Hannibal, MO](#)
[St. Louis, MO](#)
[Cape Girardeau, MO](#)
[Cairo, IL](#)

Web Information
For additional info about New River Training Structures, see the link below:
<http://www.mvs.usace.army.mil/navigation1/riverine.html>
For the most recent channel patrol and predredge surveys, see the link below:
<http://www.mvs.usace.army.mil/navigation1/Surveys.html>
The new electronic Navigation charts for the Upper Mississippi River are now available online for download or to order at the below link:
<http://www2.mvr.usace.army.mil/NIC2/mrcharts.cfm>

More Status Report
Please click for older status reports

Key	
◇	Anticipated Dredging Locations
★	Groundings
△	Dredge Potter
▽	Dredge Hurley
▽	Dredge America
Red	Very Likely to be Problematic at Low Water
Yellow	Could be Problematic at Low Water
Green	Problem Resolved

Probable "Hot" Spots Within 4 Weeks				
River Mile	Estimated Problematic Date	Dredge ETA	Dredge Complete	Dredge

Please click below to email comments or suggestions:
mvsnavstatus@usace.army.mil